

Vehicle details

VIN	VR7CCHPV8 RT167798	Registration date	13/01/2025	Exterior Color	Perla Nera Black (na
Brand	CITROEN	Licence Plate		Odometer	21 968 km
Model	New C3 1.2 Turbo 100 S&S BVM6 MAX	Condition of the car	Unknown		
Pre-damage	Unknown	Pre-damage amount excl. VAT	-	Pre-damage Comments	

Inspection Details

Inspection loc. PCD - Hödlmayr Saint-Trond



Removable element


Spare wheel kit



Technical Document

Tyres

Goodyear 205/50/17 V Summer 5.0 mm



Goodyear 205/50/17 V Summer 6.0 mm



Goodyear 205/50/17 V Summer 5.0 mm



Goodyear 205/50/17 V Summer 5.0 mm

Exterior

1



Part	Spare wheel kit
Position	-
Damages	Missing
Comments	-

2



Part	Special rim 17"
Position	Front left
Damages	Scratched
Comments	-

3



Part	Special rim 17"
Position	Back left
Damages	Scratched
Comments	-

4



Part	Special rim 17"
Position	Front right
Damages	Scratched
Comments	-

DEKRA Automotive Solutions

5		<table><tr><td>Part</td><td>Tailgate spoiler</td></tr><tr><td>Position</td><td>-</td></tr><tr><td>Damages</td><td>Improper repair</td></tr><tr><td>Comments</td><td>-</td></tr></table>	Part	Tailgate spoiler	Position	-	Damages	Improper repair	Comments	-	6		<table><tr><td>Part</td><td>Bonnet</td></tr><tr><td>Position</td><td>-</td></tr><tr><td>Damages</td><td>Scratched</td></tr><tr><td>Comments</td><td>+ overspray</td></tr></table>	Part	Bonnet	Position	-	Damages	Scratched	Comments	+ overspray
Part	Tailgate spoiler																				
Position	-																				
Damages	Improper repair																				
Comments	-																				
Part	Bonnet																				
Position	-																				
Damages	Scratched																				
Comments	+ overspray																				
7		<table><tr><td>Part</td><td>Door jamb trim</td></tr><tr><td>Position</td><td>Front left</td></tr><tr><td>Damages</td><td>Scratched</td></tr><tr><td>Comments</td><td>-</td></tr></table>	Part	Door jamb trim	Position	Front left	Damages	Scratched	Comments	-	8		<table><tr><td>Part</td><td>Door jamb trim</td></tr><tr><td>Position</td><td>Back left</td></tr><tr><td>Damages</td><td>Scratched</td></tr><tr><td>Comments</td><td>-</td></tr></table>	Part	Door jamb trim	Position	Back left	Damages	Scratched	Comments	-
Part	Door jamb trim																				
Position	Front left																				
Damages	Scratched																				
Comments	-																				
Part	Door jamb trim																				
Position	Back left																				
Damages	Scratched																				
Comments	-																				
9		<table><tr><td>Part</td><td>Door</td></tr><tr><td>Position</td><td>Back left</td></tr><tr><td>Damages</td><td>Scratched</td></tr><tr><td>Comments</td><td>-</td></tr></table>	Part	Door	Position	Back left	Damages	Scratched	Comments	-	10		<table><tr><td>Part</td><td>Tailgate / Boot door</td></tr><tr><td>Position</td><td>-</td></tr><tr><td>Damages</td><td>Improper repair</td></tr><tr><td>Comments</td><td>-</td></tr></table>	Part	Tailgate / Boot door	Position	-	Damages	Improper repair	Comments	-
Part	Door																				
Position	Back left																				
Damages	Scratched																				
Comments	-																				
Part	Tailgate / Boot door																				
Position	-																				
Damages	Improper repair																				
Comments	-																				
11		<table><tr><td>Part</td><td>Door</td></tr><tr><td>Position</td><td>Back right</td></tr><tr><td>Damages</td><td>Scratched</td></tr><tr><td>Comments</td><td>-</td></tr></table>	Part	Door	Position	Back right	Damages	Scratched	Comments	-	12		<table><tr><td>Part</td><td>Door sill</td></tr><tr><td>Position</td><td>Front right</td></tr><tr><td>Damages</td><td>Dent & Chips</td></tr><tr><td>Comments</td><td>-</td></tr></table>	Part	Door sill	Position	Front right	Damages	Dent & Chips	Comments	-
Part	Door																				
Position	Back right																				
Damages	Scratched																				
Comments	-																				
Part	Door sill																				
Position	Front right																				
Damages	Dent & Chips																				
Comments	-																				
13		<table><tr><td>Part</td><td>Door panel</td></tr><tr><td>Position</td><td>Front right</td></tr><tr><td>Damages</td><td>Dented</td></tr><tr><td>Comments</td><td>-</td></tr></table>	Part	Door panel	Position	Front right	Damages	Dented	Comments	-	14		<table><tr><td>Part</td><td>Aerial cable</td></tr><tr><td>Position</td><td>-</td></tr><tr><td>Damages</td><td>Broken</td></tr><tr><td>Comments</td><td>-</td></tr></table>	Part	Aerial cable	Position	-	Damages	Broken	Comments	-
Part	Door panel																				
Position	Front right																				
Damages	Dented																				
Comments	-																				
Part	Aerial cable																				
Position	-																				
Damages	Broken																				
Comments	-																				
15		<table><tr><td>Part</td><td>Window seal</td></tr><tr><td>Position</td><td>Front right</td></tr><tr><td>Damages</td><td>Scratched</td></tr><tr><td>Comments</td><td>-</td></tr></table>	Part	Window seal	Position	Front right	Damages	Scratched	Comments	-											
Part	Window seal																				
Position	Front right																				
Damages	Scratched																				
Comments	-																				