


Vehicle details

VIN	VR3UPHNE3 R4301981	Registration date	13/01/2025	Exterior Color	Gris Artense
Brand	PEUGEOT	Licence Plate	00xx00	Odometer	20 013 km
Model	208 Allure 1.2 Turbo100 Man.6	Condition of the car	Compliant	Pre-damage	
Pre-damage	Unknown	Pre-damage amount excl. VAT	-	Pre-damage Comments	

Inspection Details



Removable element

Emergency compressor kit	✘
Refill emergency kit	✘

Technical Document

Tyres



Exterior

1		Part	Emergency compressor kit	2		Part	Refill emergency kit
		Position	-			Position	-
4		Damages	Missing	5		Damages	Missing
		Comments	-			Comments	-
4		Part	Wing	5		Part	Door
		Position	Back left			Position	Back left
4		Damages	Dented	5		Damages	Dented
		Comments	-			Comments	sous reserve

DEKRA Automotive Solutions

<p>6</p>  <p>● ● ● ● ● ● ● ●</p>	<table border="1"> <tr><td>Part</td><td>Bumper</td></tr> <tr><td>Position</td><td>Front left</td></tr> <tr><td>Damages</td><td>Scratched</td></tr> <tr><td>Comments</td><td>-</td></tr> </table>	Part	Bumper	Position	Front left	Damages	Scratched	Comments	-	<p>7</p>  <p>● ● ● ● ●</p>	<table border="1"> <tr><td>Part</td><td>Special rim 17"</td></tr> <tr><td>Position</td><td>Front right</td></tr> <tr><td>Damages</td><td>Scratched</td></tr> <tr><td>Comments</td><td>-</td></tr> </table>	Part	Special rim 17"	Position	Front right	Damages	Scratched	Comments	-
Part	Bumper																		
Position	Front left																		
Damages	Scratched																		
Comments	-																		
Part	Special rim 17"																		
Position	Front right																		
Damages	Scratched																		
Comments	-																		
<p>8</p>  <p>● ● ●</p>	<table border="1"> <tr><td>Part</td><td>Door</td></tr> <tr><td>Position</td><td>Back right</td></tr> <tr><td>Damages</td><td>Scratched</td></tr> <tr><td>Comments</td><td>grffe profunde , no lustrage</td></tr> </table>	Part	Door	Position	Back right	Damages	Scratched	Comments	grffe profunde , no lustrage										
Part	Door																		
Position	Back right																		
Damages	Scratched																		
Comments	grffe profunde , no lustrage																		

Interior damage

<p>9</p>  <p>●</p>	<table border="1"> <tr><td>Part</td><td>Interior roof lining</td></tr> <tr><td>Position</td><td>-</td></tr> <tr><td>Damages</td><td>Stained/dirty</td></tr> <tr><td>Comments</td><td>-</td></tr> </table>	Part	Interior roof lining	Position	-	Damages	Stained/dirty	Comments	-
Part	Interior roof lining								
Position	-								
Damages	Stained/dirty								
Comments	-								

Others

<p>3</p>  <p>●</p>	<table border="1"> <tr><td>Part</td><td>Service</td></tr> <tr><td>Position</td><td>-</td></tr> <tr><td>Damages</td><td>Missing</td></tr> <tr><td>Comments</td><td>-</td></tr> </table>	Part	Service	Position	-	Damages	Missing	Comments	-
Part	Service								
Position	-								
Damages	Missing								
Comments	-								