

### Vehicle details

|            |                                     |                             |            |                     |                      |
|------------|-------------------------------------|-----------------------------|------------|---------------------|----------------------|
| VIN        | VR1J4DGZ3 RY600747                  | Registration date           | 13/09/2024 | Exterior Color      | B0MM0B B0NKKJ GRIS T |
| Brand      | DS                                  | Licence Plate               | 2CQD395    | Odometer            | 20 028 km            |
| Model      | DS 7 E-TENSE 225 PERFORMANCE LINE + | Condition of the car        | Unknown    |                     |                      |
| Pre-damage | Unknown                             | Pre-damage amount excl. VAT | -          | Pre-damage Comments |                      |

### Inspection Details

|                                                                                   |                                                                                   |                                                                                   |                                                                                   |                                                                                     |                                                                                     |
|-----------------------------------------------------------------------------------|-----------------------------------------------------------------------------------|-----------------------------------------------------------------------------------|-----------------------------------------------------------------------------------|-------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------|
| Inspection loc.                                                                   | PCD - Parc LLD                                                                    |                                                                                   |                                                                                   |                                                                                     |                                                                                     |
|  |  |  |  |  |  |
|  |  |  |  |  |  |

### Removable element

|                          |   |
|--------------------------|---|
| Emergency compressor kit | ✓ |
| Refill emergency kit     | ✓ |
| In-car tools             | ✓ |
| Toolkit                  | ✓ |
| Rear parcel shelf        | ✓ |
| Floor mat BR             | ✓ |
| Floor mat BL             | ✓ |
| Floor mat FR             | ✓ |
| Floor mat FL             | ✓ |
| Towing hook              | ✓ |
| Vehicle charger          | ✓ |
| Hook /Hicth ball         | ✓ |

### Technical Document

|                           |   |
|---------------------------|---|
| Service manual holder     | ✓ |
| Log books                 | ✓ |
| Adapter USB               | ✓ |
| Spare key                 | ✓ |
| Card Key                  | ✓ |
| Certificate of conformity | ✓ |
| Title / License document  | ✓ |
| User manual               | ✗ |
| Warranty booklet          | ✗ |

### Tyres

|                                    |                                                                                     |                                    |                                                                                      |
|------------------------------------|-------------------------------------------------------------------------------------|------------------------------------|--------------------------------------------------------------------------------------|
| Michelin 235/50/19 V Summer 6.0 mm |  | Michelin 235/50/19 V Summer 6.0 mm |  |
| Michelin 235/50/19 V Summer 7.0 mm |  | Michelin 235/50/19 V Summer 7.0 mm |  |

### Exterior

|   |                                                                                      |          |                 |
|---|--------------------------------------------------------------------------------------|----------|-----------------|
| 1 |   | Part     | Alloy wheel 19" |
|   |                                                                                      | Position | Front left      |
|   |                                                                                      | Damages  | Scratched       |
|   |                                                                                      | Comments | -               |
| 2 |  | Part     | Door            |
|   |                                                                                      | Position | Front left      |
|   |                                                                                      | Damages  | Scratched       |
|   |                                                                                      | Comments | -               |

**DEKRA Automotive Solutions**

3



Part

Bumper

Position

Back

Damages

Scratched

Comments

-

5



Part

Door

Position

Front right

Damages

Dented

Comments

-

6



Part

Windscreen with camera

Position

-

Damages

Stone impact

Comments

-

**Interior damage**

7



Part

User manual

Position

-

Damages

Missing

Comments

FR

8



Part

Warranty booklet

Position

-

Damages

Missing

Comments

FR

**Others**

4



|          |              |
|----------|--------------|
| Part     | Charging kit |
| Position | -            |
| Damages  | Missing      |
| Comments | Si standard  |