

Vehicle details

VIN	VR1J45GBU PY679427	Registration date	20/12/2024	Exterior Color	Gris Laqu
Brand	DS	Licence Plate	2GLG318	Odometer	5 321 km
Model	DS 7 E-TENSE 360 RIVOLI	Condition of the car	Mediocre		
Pre-damage	Unknown	Pre-damage amount excl. VAT	-	Pre-damage Comments	

Inspection Details

Inspection loc.	PCD - Parc LLD				
-----------------	----------------	--	--	--	--



Removable element

Emergency compressor kit	✓
Refill emergency kit	✓
In-car tools	✓
Toolkit	✓
Rear parcel shelf	✓
Floor mat BR	✓
Floor mat BL	✓
Floor mat FR	✓
Floor mat FL	✓
Towing hook	✓
Vehicle charger	✓

Technical Document

Service manual holder	✓
User manual	✓
Warranty booklet	✓
Log books	✓
Adapter USB	✓
Spare key	✓
Card Key	✓
Certificate of conformity	✓
Title / License document	✓

Tyres

Michelin 245/35/21 Y Summer 6.0 mm		Michelin 245/35/21 Y Summer 6.0 mm	
Michelin 245/35/21 Y Summer 5.0 mm		Michelin 245/35/21 Y Summer 5.0 mm	

Exterior

1		Part	Spoiler	2		Part	Bonnet
		Position	Front			Position	-
		Damages	Deformed			Damages	Chemical deposit
		Comments	-			Comments	S.R.

DEKRA Automotive Solutions

3



Part	Special rim 21"
Position	Front left
Damages	Scratched
Comments	-

4



Part	Special rim 21"
Position	Back left
Damages	Scratched
Comments	S.R.

5



Part	Window
Position	Back right
Damages	Broken
Comments	-

6



Part	Special rim 21"
Position	Back right
Damages	Scratched
Comments	S.R.

7



Part	Upper tailgate / Boot
Position	-
Damages	Chemical deposit
Comments	S.R.

8



Part	Special rim 21"
Position	Front right
Damages	Scratched
Comments	S.R.

9



Part	Tyre
Position	Back right
Damages	Cut
Comments	-

10



Part	Tyre
Position	Front right
Damages	Cut
Comments	-

Interior damage

11



Part	Interior cleaning
Position	-
Damages	Not carried out
Comments	-

Comments

Véhicule déposé par un chauffeur et reparti avec la nouvelle voiture sans signature