

## Vehicle details

|            |                                |                             |            |                     |                       |
|------------|--------------------------------|-----------------------------|------------|---------------------|-----------------------|
| VIN        | VR7CCHPV9 ST054321             | Registration date           | 14/04/2025 | Exterior Color      | Mercury Grey (metall) |
| Brand      | CITROEN                        | Licence Plate               | 2GVR418    | Odometer            | 16 205 km             |
| Model      | New C3 Turbo 100 ch Manual MAX | Condition of the car        | Unknown    |                     |                       |
| Pre-damage | Unknown                        | Pre-damage amount excl. VAT | -          | Pre-damage Comments |                       |

## Inspection Details

Inspection loc. PCD - Hödlmayr Saint-Trond



## Removable element

|                          |   |
|--------------------------|---|
| Refill emergency kit     | ✓ |
| Rear parcel shelf        | ✓ |
| Emergency compressor kit | ✗ |

## Technical Document

## Tyres

Goodyear 205/50/17 V Summer 7.0 mm



Goodyear 205/50/17 V Summer 7.0 mm



Goodyear 205/50/17 V Summer 7.0 mm

Goodyear 205/50/17 V Summer 7.0 mm

## Exterior

|   |                                                                                     |          |                          |   |                                                                                      |          |                 |
|---|-------------------------------------------------------------------------------------|----------|--------------------------|---|--------------------------------------------------------------------------------------|----------|-----------------|
| 1 |  | Part     | Engine soundproofing     | 2 |  | Part     | Special rim 17" |
|   |                                                                                     | Position | -                        |   |                                                                                      | Position | Front right     |
|   |                                                                                     | Damages  | Cut                      |   |                                                                                      | Damages  | Scratched       |
|   |                                                                                     | Comments | -                        |   |                                                                                      | Comments | -               |
| 3 |  | Part     | Emergency compressor kit | 4 |  | Part     | Aerial cable    |
|   |                                                                                     | Position | -                        |   |                                                                                      | Position | Centre          |
|   |                                                                                     | Damages  | Missing                  |   |                                                                                      | Damages  | Missing         |
|   |                                                                                     | Comments | -                        |   |                                                                                      | Comments | -               |

## Comments

Parc stockage : OV - Hödlmayr Saint-Trond