

### Vehicle details

|            |                             |                             |            |                     |             |
|------------|-----------------------------|-----------------------------|------------|---------------------|-------------|
| VIN        | VR3USHPY6 SJ603438          | Registration date           | 25/03/2025 | Exterior Color      | Artens Gris |
| Brand      | PEUGEOT                     | Licence Plate               | 00xx23     | Odometer            | 29 508 km   |
| Model      | 2008 GT Hybrid 145ch e-DSC6 | Condition of the car        | Compliant  |                     |             |
| Pre-damage | Unknown                     | Pre-damage amount excl. VAT | -          | Pre-damage Comments |             |

### Inspection Details

|                                                                                   |                                                                                   |                                                                                   |                                                                                   |                                                                                     |                                                                                     |
|-----------------------------------------------------------------------------------|-----------------------------------------------------------------------------------|-----------------------------------------------------------------------------------|-----------------------------------------------------------------------------------|-------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------|
| Inspection loc.                                                                   | PCD - Hödlmayr Saint-Trond                                                        |                                                                                   |                                                                                   |                                                                                     |                                                                                     |
|  |  |  |  |  |  |
|  |  |  |  |  |  |

### Removable element

|                          |   |
|--------------------------|---|
| Refill emergency kit     | ✓ |
| Emergency compressor kit | ✗ |

### Technical Document

### Tyres

|                                         |                                                                                     |                                         |                                                                                       |
|-----------------------------------------|-------------------------------------------------------------------------------------|-----------------------------------------|---------------------------------------------------------------------------------------|
| Michelin 215/60/17 H All seasons 5.0 mm |  | Michelin 215/60/17 H All seasons 5.0 mm |  |
| Michelin 215/60/17 H All seasons 5.0 mm |  | Michelin 215/60/17 H All seasons 5.0 mm |    |

### Exterior

|   |                                                                                     |                                                                                  |   |                                                                                      |                                                                                   |
|---|-------------------------------------------------------------------------------------|----------------------------------------------------------------------------------|---|--------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------|
| 1 |  | Part: Emergency compressor kit<br>Position: -<br>Damages: Missing<br>Comments: - | 3 |  | Part: Door<br>Position: Back left<br>Damages: Dent & Chips<br>Comments: -         |
| 5 |  | Part: Roof<br>Position: -<br>Damages: Dented<br>Comments: -                      | 6 |  | Part: Tailgate / Boot door<br>Position: -<br>Damages: Dent & Chips<br>Comments: - |

### Interior damage

|   |                                                                                    |          |                  |
|---|------------------------------------------------------------------------------------|----------|------------------|
| 2 |   | Part     | Fabric seat      |
|   |                                                                                    | Position | -                |
|   |                                                                                    | Damages  | Stained/dirty    |
|   |                                                                                    | Comments | -                |
|   |                                                                                    |          |                  |
| 4 |  | Part     | Fabric seat back |
|   |                                                                                    | Position | Back left        |
|   |                                                                                    | Damages  | Broken           |
|   |                                                                                    | Comments | tirette cassee   |
|   |                                                                                    |          |                  |