

Vehicle details

VIN	VR3KAHPY1 RS145922	Registration date	03/02/2025	Exterior Color	Gris Titane
Brand	PEUGEOT	Licence Plate		Odometer	11 155 km
Model	New 3008 First Edition Allure Hybrid 136 e-DCS6	Condition of the car	Compliant		
Pre-damage	Unknown	Pre-damage amount excl. VAT	-	Pre-damage Comments	

Inspection Details


Inspection loc. PCD - Hödlmayr Saint-Trond



Removable element

Emergency compressor kit	✓
Refill emergency kit	✓

Technical Document



Tyres



Michelin 225/55/19 V Summer 5.0 mm

Exterior

 <p>1</p>	<table border="1"> <tr><td>Part</td><td>Bumper</td></tr> <tr><td>Position</td><td>Back left</td></tr> <tr><td>Damages</td><td>Scratched</td></tr> <tr><td>Comments</td><td>-</td></tr> </table>	Part	Bumper	Position	Back left	Damages	Scratched	Comments	-	 <p>2</p>	<table border="1"> <tr><td>Part</td><td>Unpainted bumper</td></tr> <tr><td>Position</td><td>Back</td></tr> <tr><td>Damages</td><td>Dented</td></tr> <tr><td>Comments</td><td>-</td></tr> </table>	Part	Unpainted bumper	Position	Back	Damages	Dented	Comments	-
	Part	Bumper																	
	Position	Back left																	
Damages	Scratched																		
Comments	-																		
Part	Unpainted bumper																		
Position	Back																		
Damages	Dented																		
Comments	-																		
 <p>3</p>	<table border="1"> <tr><td>Part</td><td>Door</td></tr> <tr><td>Position</td><td>Front right</td></tr> <tr><td>Damages</td><td>Stone impact</td></tr> <tr><td>Comments</td><td>-</td></tr> </table>	Part	Door	Position	Front right	Damages	Stone impact	Comments	-										
	Part	Door																	
	Position	Front right																	
Damages	Stone impact																		
Comments	-																		